

# DMI Medical Garments

## Medical Compression Garments

### Measurement Guidelines - Female

In order to help us get the best possible fit for the garment, please take the following measurements. Please take the measurements in **inches** and measure as indicated below.

Breast:	Around the fuller part of the bust (while wearing a bra), across the nipples.
Contour:	Around the chest, under the breast area, with bra on.
Waist:	Around the body going across the belly button.
Hips:	Around fuller part of buttocks and lining up in front with the crease at the top of the leg ("panty line") so tape comes to top of pubic area.
Thigh:	Taken around fullest part of upper thigh, parallel to the floor. Take measurements on both legs.
Biceps:	Taken across the fullest part of the upper arms. Take measurements on both arms. Arms should hang relaxed at your sides.
Torso:	In cases where a patient is shorter or taller than the average person, a torso measurement needs to be taken. Please measure from the bottom of the sternum to the top of the pubic bone.

